
BROOKHAVEN NATIONAL LABORATORY Safety & Health Services Division INDUSTRIAL HYGIENE GROUP Standard Operating Procedure: Field Procedure SUBJECT: INSTRUMENT OPERATION: GenRad 1982 As an Octave Band Analyzer NUMBER IH96401 REVISION Final Rev4 DATE 11/02/05 PAGE 1 OF 15

Contents

- 1.0 Purpose/Scope
- 2.0 Responsibilities
- 3.0 Definitions
- 4.0 Prerequisites
- 5.0 Precautions
- 6.0 Procedure
- 7.0 Implementation and Training
- 8.0 References
- 9.0 Attachments
- 10.0 Documentation





1.0 Purpose/Scope

This procedure provides a standardized method for the calibration and operation of the GenRad GR1982 as an Octave Band Analyzer (OBA). It should be used in conjunction with the SBMS Subject Area *Noise and Hearing Conservation* and IH SOP IH96200 *Noise Measurement Principles: Area Surveys.*

The GenRad 1982, when used as an OBA, is used to determine the sound pressure level at octave bands from 31Hz to 16kHz to evaluate problem-noise sources and measuring the effectiveness of engineering controls.

2.0 Responsibilities

- 2.1 Use of the GenRad 1982 shall be limited to persons who act under the direction of a competent hazard assessment person and have demonstrated the competency to satisfactorily use the meter, as evidenced by experience and training, to the satisfaction of their supervision or existing qualification criteria set by BNL.
- 2.2 Personnel that perform exposure monitoring with this instrument are responsible to follow all steps in this procedure.

BROOKHAVEN NATIONAL LABORATORY Safety & Health Services Division		NUMBER IH96401
	REVISION Final Rev4	
SUBJECT:	INSTRUMENT OPERATION: GenRad 1982	DATE 11/02/05
	As an Octave Band Analyzer	PAGE 2 OF 15

2.3 The data collected using this meter must have an appropriate evaluation of the hazard and risk by a skilled Industrial Hygiene professional.

3.0 **Definitions**

- 3.1 Decibel(dB): A non-dimensional unit used to express sound pressure levels. It is the log of the ratio of the measured sound pressure level to a reference level.
 - 3.1.1 *dBA*: A sound pressure level in decibels made on the A-scale of a sound level meter. This unit of measure approximates the response of the human ear.
 - 3.1.2 *dBC*: Sound pressure based on a nearly flat, non-weighted scale.
- 3.2 *Frequency:* The number of cycles completed by a periodic quantity in a unit time. Unit, hertz (Hz) measures cycles per second.
- 3.3 *Impulse or Impact Noise Levels:* Variations in noise levels that involve peak levels spaced at periods of greater than one per second. Where the intervals are less than one second, it should be considered a continuous noise source.
- 3.4 Occupational Exposure Limit: The maximum time weighted average (TWA) exposure permitted for employee exposure, based on the less of the OSHA Permissible Exposure Limits (PEL) or ACGIH Threshold Limit Value (TLV). See IH96200.

4.0 Prerequisites

4.1 Training prior to using this meter:

- 4.1.1 Demonstration of proper operation of the instrument per the qualification criteria set by BNL. Refer to Section 7 *Implementation and Training*.
- 4.1.2 Other appropriate training for other hazards in the area to be entered may be needed. Check with ESH coordinator or FS Representative for the facility.

4.2 Area Access:

- 4.2.1 Contact the appropriate Facility Support Representative or Technician to obtain approval to enter radiological areas.
- 4.2.2 Verify with the appropriate Facility Support Representative or Technician if a Work Permit or Radiological Permit is needed or is in effect. If so, review and sign the permit.
- 4.2.3 Use appropriate PPE for area

BROOKHAVEN NATIONAL LABORATORY Safety & Health Services Division		NUMBER IH96401
	INDUSTRIAL HYGIENE GROUP Standard Operating Procedure: Field Procedure	REVISION Final Rev4
SUBJECT:	INSTRUMENT OPERATION: GenRad 1982	DATE 11/02/05
	As an Octave Band Analyzer	PAGE 3 OF 15

5.0 Precautions

5.1 Hazard Determination:

- 5.1.1 The operation of this meter does not cause exposure to any chemical, physical, or radiological hazards. The meter design does not cause significant ergonomic concerns in routine use. The meter does not generate Hazardous Waste.
- 5.1.2 By its very nature, the GenRad meter may be used in areas where excessive noise levels exist or are suspected to be present. Exposures to noise levels above the PEL and/or TLV may cause temporary or permanent hearing loss.

5.2 Personal Protective Equipment:

- 5.2.1 In areas where noise levels exceed the *Occupational Exposure Limit (OEL)*, hearing protection should be worn. The hearing protection should be able to reduce the noise levels below the OEL. See IH96200 for guidance on PPE selection.
- 5.2.2 Additional PPE: Other appropriate PPE for the area being entered. Check with your ES&H representative.

6.0 Procedure

Equipment: (Pictured in Appendix 9.1)

- Meter Body
- Microphone
- Calibration screwdriver
- Calibrator

Operation of the GenRad (picture of meter and description of controls and displays is contained in Appendix 9.1.)

6.1 **Battery Check**

- 6.1.1 Slide the Power switch to the \mathbb{BAT} and hold it there briefly.
- 6.1.2 Verify that the meter pointer indicates in the $\mathbb{BAT} \# \mathbb{A}$ areas and that the digital display indicates $\mathbb{SS} . \mathbb{S}$. If it does not, recharge battery.
- 6.1.3 Perform the battery check at least once every half hour of use.

BROOKHAVEN NATIONAL LABORATORY Safety & Health Services Division		IH96401
	INDUSTRIAL HYGIENE GROUP Standard Operating Procedure: Field Procedure	REVISION Final Rev4
SUBJECT:	INSTRUMENT OPERATION: GenRad 1982	DATE 11/02/05
	As an Octave Band Analyzer	PAGE 4 OF 15

6.2 **Warm-up:** A warm-up is not required for this meter.

6.3 Calibration:

- 6.3.1 Verify that the calibrator battery checks ok.
- 6.3.2 Slide the *Power Switch* to *ON* and the *DIGITAL DISPLAY* switch to *CONT*.
- 6.3.3 Set the *Octave Filter* switch to \mathbb{WTG} , the *WEIGHTING* switch to \mathbb{A} , and the *Detector* switch to \mathbb{SLOW} . Select the 70 to 120 dB range.
- 6.3.4 Turn the calibrator on.
- 6.3.5 Place the calibrator, with ½ inch coupler/adaptor installed, over the microphone of the sound level meter (SLM).
- 6.3.6 Observe that both the SLM pointer and the digital display indicate 114 (plus or minus 0.5 dB). Check the meter response at each frequency band. Record reading on both the dBA and dBC weighting scales and each frequency. If the indication is outside this range, adjust the CAL control.

6.4 **Operation:**

- 6.4.1 Select the desired weighting by sliding the *WEIGHTING* switch to $A_{\mathfrak{p}} \mathbb{B}_{\mathfrak{p}} \mathbb{C}$ or \mathbb{FLAT} . For occupational exposure monitoring the setting should be \mathbb{A} .
- 6.4.2 Move the *OCTAVE FILTER* switch to each frequency band and record the meter reading on the data form. Also test the noise level with the meter in the WTG position.
- 6.4.3 Select desired detector characteristic by sliding the *DETECTOR* switch to *FAST*, *IMP*, *PEAK*, or *SLOW*. The detector can be reset in either the *IMP* or *PEAK* modes by depressing the *CAPTURE* button momentarily. For occupational exposure monitoring the setting should be Slow.
- 6.4.4 Adjust the *dB RANGE* switch for an on-scale meter indication and read the meter or digital display. If the *OVERLOAD* lamp is lit, adjust the *dB RANGE* switch to a higher range.

6.5 **Digital Display:**

- 6.5.1 For a display that duplicates the meter indication, set the *DIGITAL DISPLAY* switch to \mathbb{CONT} . The display will now track the meter indication.
- 6.5.2 To capture a measurement, slide the *DIGITAL DISPLAY* switch to *CONT* and at the desired moment, press and hold the *CAPTURE* button. The digital display will be "frozen" as long as the *CAPTURE* button is held.
- 6.5.3 To capture the maximum indication during a measurement period, slide the *DIGITAL DISPLAY* switch to *MAX*. Press the *CAPTURE* button and release

BROOKHAVEN NATIONAL LABORATORY Safety & Health Services Division INDUSTRIAL HYGIENE GROUP Standard Operating Procedure: Field Procedure SUBJECT: INSTRUMENT OPERATION: GenRad 1982 As an Octave Band Analyzer NUMBER IH96401 REVISION Final Rev4 DATE 11/02/05 PAGE 5 OF 15

it to begin the measurement period.

- 6.6 **Operator Position:** Preferably the operator should be further from the sound source than the microphone and positioned as to reduce reflection of the sound to the meter. Hold the meter at arms length.
 - 6.6.1 DO NOT stand between the sound source and microphone.
 - 6.6.2 DO NOT place the hand within 12 cm (5 inches) of the microphone.
 - 6.6.3 The microphone is a "flat-random-incidence-response type". Do not point the meter at the source, hold it at a $\frac{70-90 \text{ degree angle}}{1000 \text{ from the noise source}}$, i.e., take the measurement so that the path from the noise source to the microphone is along a $\frac{70^0 \text{ to } 90^0}{1000}$.)
 - 6.6.4 Take measurements at ear level of employee (sitting, standing or bending) to estimate personal exposures and to locate isometric lines of noise intensity on a sketch for defining area levels.
 - 6.6.5 Perform a post calibration as per step 6.3.

6.7 **Recording readings:**

- 6.7.1 Use the BNL Direct Reading Sampling Instrument Form to record readings (see the IH web page for the most recent version).
- 6.7.2 Return meter and original sampling form to the SHSD IH Laboratory daily or at the end of each project as agreed to by the IH Laboratory Technician.
- 6.7.3 Send a copy of any hazard evaluation report written on the survey to the IH Laboratory and the Occupational Medicine Clinic.

7.0 Implementation and Training

- 7.1 Training prior to using this meter includes a demonstration of proper operation of the instrument based on training, education, and experience. All persons must have met the qualification criteria for IH96 Noise Assessor set in *IH50300 BNL IH Program and IH Group Training & Qualification Matrix*.
- 7.2 Personnel are to document their training using Attachment 9.5, the Job Performance Measure Completion Certificate. Qualification on this JPM is required on a 3 year basis, providing the professional is monitoring noise sources frequently.

BROOKHAVEN NATIONAL LABORATORY Safety & Health Services Division		NUMBER IH96401
	REVISION Final Rev4	
SUBJECT:	INSTRUMENT OPERATION:	DATE 11/02/05
GenRad 1982 As an Octave Band Analyzer		PAGE
	As all Octave Dalla Allalyzei	6 OF 15

- 7.3 A baseline audiogram may be needed if the duration of exposure to the person performing the survey will be in excess of the OSHA Permissible Exposure Limits (PEL) or ACGIH Threshold Limit Value (TLV) (which ever is less). See IH96200.
- 7.4 Other appropriate training for the area to be entered (check with ESH coordinator or FS Representative for the facility).

8.0 References

- 8.1 GenRad GR 1982 Precision Sound-Level Meter and Analyzer Instruction Manual.
- 8.2 BNL SBMS Subject Area Noise and Hearing Conservation.
- 8.3 OSHA Noise/Hearing Conservation 29CFR1910.95.
- 8.4 NIOSH Criteria for a Recommended Standard-Occupational Noise Exposure, 1998.
- 8.5 ACGIH American Conference of Governmental Industrial Hygienists Threshold Limit Values for Chemical Substances and Physical Agents and Biological Exposure Indices.

9.0 Attachments

- 9.1 Photo of meter and parts
- 9.2 Theory of Operation
- 9.3 Short List of Operating Instructions
- 9.4 Octave Band Analysis: Area Survey Form
- 9.5 Job Performance Measure Completion Certificate

10.0 Documentation

BROOKHAVEN NATIONAL LABORATORY Safety & Health Services Division INDUSTRIAL HYGIENE GROUP Standard Operating Procedure: Field Procedure SUBJECT: INSTRUMENT OPERATION: GenRad 1982 As an Octave Band Analyzer NUMBER IH96401 REVISION Final Rev4 11/02/05 PAGE 7 OF 15

Document Dev	Document Development and Revision Control Tracking			
Prepared By: (Signature and date on file) R. Selvey Author Date 03/14/01	Reviewed By: (Signature and date on file) J. Peters SHSD IH Group Date 03/15/01	Approved By: (Signature and date on file) R. Selvey SHSD IH Group Leader Date 03/15/01		
ESH Coordinator/ Date:	Work Coordinator/ Date:	SHSD Manager / Date		
none	none	none		
QA Representative / Date: none	Training Coordinator / Date:	Filing Code: IH52		
Facility Support Rep. / Date:	Environ. Compliance Rep. / Date:	Effective Date:		
none	none	06/08/01		
ISM Review - Hazard Categorization ☐ High ☑ Moderate ☐ Low/Skill of the craft	Validation: ☐ Formal Walkthrough ☐ Desk Top Review ☐ SME Review Name / Date:	Implementation: Training Completed: Tracked in BTMS Procedure posted on Web: 11/02/05 Hard Copy files updated: 11/02/05		
Revision Log				


Revision Log			
Purpose: Temporary Change Chang	je in Scope 🗌 Periodic review 🛭 Clarify/enh	nance procedural controls	
Changed resulting from: ☐ Environmental to non-conformances ☒ none of the above	impacts Federal, State and/or Local require	rements	
Section/page and Description of change: Co	prrected error in Section 6.2.3.6		
(signature on file) R. Selvey 12/30/03 SME Reviewer/Date:	(signature on file) J. Peters 12/30/03 Reviewer/Date:	Reviewer/Date:	
Purpose: Temporary Change Chang	je in Scope 🛛 Periodic review 🗌 Clarify/enh	nance procedural controls	
Changed resulting from: ☐ Environmental to non-conformances ☒ none of the above	impacts	rements	
Section/page and Description of change: ReSBMS. Updated reference to JPM in IH961	evised format with Section 7 as Implementation 20.	n and Training. Updated references to	
(signature on file) R. Selvey 04/12/04 SME Reviewer/Date:	Reviewer/Date:	Reviewer/Date:	
Purpose: ☐ Temporary Change ☐ Change in Scope ☐ Periodic review ☒ Clarify/enhance procedural controls			
Changed resulting from: ☐ Environmental impacts ☐ Federal, State and/or Local requirements ☐ Corrective/preventive actions to non-conformances ☐ none of the above			
Section/page and Description of change: Added Attachment 9.5. Change in Section 7.			
(signature on file) R. Selvey 07/12/04 SME Reviewer/Date: Reviewer/Date: Reviewer/Date:			

BROOKHAVEN NATIONAL LABORATORY Safety & Health Services Division		NUMBER IH96401
	REVISION Final Rev4	
SUBJECT:	INSTRUMENT OPERATION: GenRad 1982	DATE 11/02/05
	As an Octave Band Analyzer	PAGE 8 OF 15

Purpose: ☐ Temporary Change ☐ Change in Scope ☐ Periodic review ☐ Clarify/enhance procedural controls				
Changed resulting from: ☐ Environmental impacts ☐ Federal, State and/or Local requirements ☐ Corrective/preventive actions to non-conformances ☒ none of the above				
Section/page and Description of change: Revised Section 7 training requirements. Updated Section 10 to new format.				
(signature/date on file) R. Selvey 11/02/05				
SME Reviewer/Date:	SME Reviewer/Date:	SME Reviewer/Date:		

	BROOKHAVEN NATIONAL LABORATORY Safety & Health Services Division	NUMBER IH96401
	INDUSTRIAL HYGIENE GROUP Standard Operating Procedure: Field Procedure	REVISION Final Rev4
SUBJECT:	INSTRUMENT OPERATION:	DATE 11/02/05
l	GenRad 1982	PAGE
	As an Octave Band Analyzer	9 OF 15

Attachment 9.1 Photo of the Meter and Parts



	BROOKHAVEN NATIONAL LABORATORY Safety & Health Services Division	NUMBER IH96401
	INDUSTRIAL HYGIENE GROUP Standard Operating Procedure: Field Procedure	REVISION Final Rev4
SUBJECT:	INSTRUMENT OPERATION: GenRad 1982	11/02/05
	As an Octave Band Analyzer	PAGE 10 OF 15

Attachment 9.2

Theory of Operation

The GenRad GR 1982 is a precision sound level meter which incorporates octave-band filters from 31.5 Hz to 16 kHz, A, B, C and Flat weighting networks, as well as FAST, SLOW, IMPACT and IMPULSE detector response. The sound pressure is displayed on a 50-dB linear scale. The meter utilizes a 4-digit display that follows the analog meter indication with a 0.1 dB resolution.

- A reading can be captured on the digital display at the precise instant required while the analog meter continues to track the incoming noise level
- The digital display can be used in the continuous mode or it can be operated to capture and hold the maximum level encountered. This is extremely useful when measuring sounds of short duration or vehicle "passerby" sounds.
- In the maximum mode, the digital display will be updated by the highest sound level. The display can be reset by pressing a button.
- In the peak (impact) or impulse modes, the peak detector can be reset by the press of a button. This allows other readings to be taken without waiting for the peak detector to decay.

Weighting Networks. The meter contains three weighting networks, A, B, C, which shape the noise to discriminate against the frequency components of the measured noise.

- A Network: Simulates subjective responses to noise. Generally used in noise surveys to locate noise hazards. The A Network discriminates the low frequencies quite severely Most regulations require that noise be measured on the A-weighting scale.
- B Network: Moderately discriminates (filters) against low frequencies
- C Network: Barely discriminates (filters) against low frequencies.

If measured sound levels of noise are much higher on the C-weighting than on the A- weighting, much of the noise is contributed by the low frequencies.

BROOKHAVEN NATIONAL LABORATORY Safety & Health Services Division		NUMBER IH96401
	INDUSTRIAL HYGIENE GROUP Standard Operating Procedure: Field Procedure	REVISION Final Rev4
SUBJECT:	INSTRUMENT OPERATION:	DATE 44/00/05
	GenRad 1982	11/02/05
	As an Octave Band Analyzer	PAGE 11 OF 15

Attachment 9.3

Short Operating Instructions

	Step	User Action	Digital Display
1	Battery Check	Slide power switch to battery – hold briefly. Pointer	&&&. &
		should indicate $BAT Ok$	
2	Pre-	Power switch <i>ON</i>	CONT
	Calibration	Octave Filter switch – <i>WTG</i>	
		Weighting Switch to A	
		Detector Switch to <i>SLOW</i>	Select 70-120 dB
		Turn Calibrator on and place over microphone of meter	range: meter reading
		(using installed ½ inch coupler/adaptor). Record meter	of II4 (plus or minus
		reading at each frequency from 31 Hz to 16kHz.	5 dB) is acceptable.
3	Operator	Stand at the same distance from sound source as the	
	Position	microphone. Hold Meter at arms length.	
4	Operation	Select Weighting Switch to A, B, C or FLAT	
		Select Detector Switch to <i>FAST</i> , <i>IMP</i> , <i>PEAK</i> or <i>Slow</i>	
		Adjust <i>dB range</i> to keep meter on scale	
		Record meter reading at each frequency from 31 Hz to	
		16kHz.	
5	Capturing	Slide Digital Display Switch to <i>CONT</i> and press	
	Measurement	CAPTURE button.	
		To capture maximum dB level during measurement,	
		slide Digital Display Switch to MAX and Press	
		CAPTURE button.	
6	Post	Repeat Step 2.	
	Calibration		

	BROOKHAVEN NATIONAL LABORATORY Safety & Health Services Division	NUMBER IH96401
	INDUSTRIAL HYGIENE GROUP Standard Operating Procedure: Field Procedure	REVISION Final Rev4
SUBJECT:	INSTRUMENT OPERATION: GenRad 1982	DATE 11/02/05
	As an Octave Band Analyzer	PAGE 12 OF 15

Attachment 9.4

Octave Band Analysis Area Survey Form

(next page)

(form is two sided)

BROOKHAVEN NATIONAL LABOR Environment, Safety, Health and Qua		rate											ALYSIS NT FORM				
DATE:		SURV	EYOR(S)):													
I. AREA INFORMATION																	
DEPT:		BLDG	:					ROOM	:								
SOURCE:																	
ENGINEERING CONTROLS:																	
II. EMPLOYEE INFORMATION		1						Ī									
FIRST NAME:		NAME:					BNL #:										
DEPT:	BLDG						JOB TI										
EXPOSURE DURATION (HRS):		EXPC	SURE (T	IMES PE	R DAY):		EXPOS	SURE (DA	YS PEF	R YR):							
JOB PERFORMED:																	
PPE USED:																	
III. SURVEY INSTRUMENT INFORM	ATION																
INSTRUMENT:	MODE	EL:					SERIAL#:										
FACTORY CALIBRATION DATE:		PRE-0	CAL:	В	Y :			POST CAL: BY:									
BATTERY CHECK (Y/N):		125	250	500	1000			125	250	500	1000	2000					
CALIBRATOR SERIAL #:	dBA						dBA										
		dBC						dBC									
IV. SAMPLING INFORMATION & RE	SULTS																
Response:FASTSLOW	PEAK	IMP	ULSE	Weigh	ting:	_A	_BC	Flat			WIND	SCREE	N: Y N				
LOCATION OF SAMPLE	WGT	31	62	125	25	50	500	1000	2000	400	0	8000	16000				
											\top						
											\top						
Additional Data on page 2	<u> </u>		<u> </u>		<u> </u>	<u> </u>			<u> </u>	1							
	ATIONS																
V. CONCLUSIONS & RECOMMEND	ATIONS																
Return completed form to: IH Lab, Bu	ilding 129A	\						FILE CO	DE: IH698	SR. I	FORM	1 IH9630 ²	1 (03/01)				

IH96301 Page 2

IV. SAMPLING INFORMATION & RESULTS												
LOCATION OF SAMPLE	WGT	31	62	125	250	500	1000	2000	4000	8000	16000	

`	· •.	. •	Ο,			•	AR	 . (<u> </u>		,	-/																				
•	•	•	•	•	•	٠	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•	•
•	•	•	•	•	•	٠	•	•	•	•	٠	•	•	•	•	٠	•	•	٠	•	٠	•	•	•	•	٠	•	•	•	•	٠	•
•	•	•	٠	•	•	٠	•	•	•	٠	٠	•	•	٠	•	٠	•	•	٠	•	٠	•	•	•		•	•	•	•	٠	•	•
•	٠	•	٠	•	•	٠	•	•	•	•	٠	•	•	•	•	٠	•	•	٠	•	٠	•	•	•	•	•	•	•	•	•	•	•
					•	٠	٠				٠				•		٠														•	•
•	•	•			•		-						•		•		•	•				•				•		•		•	•	
													,					,														
																•																
•														•							•											
•							•																						•			
•	•	•		•	•		•	•	•	•					•	•	•		•		•		•			•			•		•	•
•		•	•		•	•	•	•	•		•	•	•	•	•	•	•	•	•		•	•	•	•	•	•	•	•	•	•	•	•

HP-IHP-96401

Industrial Hygiene Program IH 96401 Attachment 9.5

Noise and Hearing Conservation Operation of the GenRad 1982 OBA Meter

Candidate's Name



Life Number:

Job Performance Measure	(JPM) Completion	Certificate
-------------------------	------------------	-------------

Understands the need to perform a hazard analysis of the area	1							
and potential exposure to the self as sampler and workers in the area.								
Understands the need to be aware of the potential surface contamination, airborne levels of contaminants, radiological hazards, and noise hazard. Knows how to determine the need for PPE.								
Knows where equipment needed for the procedure is located and how to properly sign it out.								
Knows the theory to establish operating parameters (safety envelope) for the equipment.								
Demonstrates correctly filling out IH monitoring forms.								
	Of Me	Recov.	olog Satisf					
Demonstrates correctly activating the meter and turning it off								
Demonstrates correctly calibrating/bump checking the meter								
Demonstrates the correctly to erase stored data								
Demonstrates correctly hold the meter, and the correct settings								
Demonstrates correctly extracting stored data from the meter to paper printout and electronic storage.								
Demonstrates correctly for removing stored data for the next user.								
lity for performing this task as demonstrated within t	his JP	M and	the					
Corresponding SOP. Candidate Signature:								
	steps	and i	s					
Evaluator Signature:								
- -	Understands the need to be aware of the potential surface contamination, airborne levels of contaminants, radiological hazards, and noise hazard. Knows how to determine the need for PPE. Knows where equipment needed for the procedure is located and how to properly sign it out. Knows the theory to establish operating parameters (safety envelope) for the equipment. Demonstrates correctly filling out IH monitoring forms. Ation - Practical Skill Evaluation: Demonstration Qualifying Performance Standard Demonstrates correctly activating the meter and turning it off Demonstrates correctly calibrating/bump checking the meter Demonstrates the correctly to erase stored data Demonstrates correctly extracting stored data from the meter to paper printout and electronic storage. Demonstrates correctly for removing stored data for the next user.	Understands the need to be aware of the potential surface contamination, airborne levels of contaminants, radiological hazards, and noise hazard. Knows how to determine the need for PPE. Knows where equipment needed for the procedure is located and how to properly sign it out. Knows the theory to establish operating parameters (safety envelope) for the equipment. Demonstrates correctly filling out IH monitoring forms. Ation - Practical Skill Evaluation: Demonstration of Me Qualifying Performance Standard Demonstrates correctly activating the meter and turning it off Demonstrates correctly calibrating/bump checking the meter Demonstrates the correctly to erase stored data Demonstrates correctly hold the meter, and the correct settings Demonstrates correctly extracting stored data from the meter to paper printout and electronic storage. Demonstrates correctly for removing stored data for the next user. It is for performing this task as demonstrated within this JP Date:	Understands the need to be aware of the potential surface contamination, airborne levels of contaminants, radiological hazards, and noise hazard. Knows how to determine the need for PPE. Knows where equipment needed for the procedure is located and how to properly sign it out. Knows the theory to establish operating parameters (safety envelope) for the equipment. Demonstrates correctly filling out IH monitoring forms. Attion - Practical Skill Evaluation: Demonstration of Method Qualifying Performance Standard Demonstrates correctly activating the meter and turning it off Demonstrates correctly calibrating/bump checking the meter Demonstrates the correctly to erase stored data Demonstrates correctly extracting stored data from the meter to paper printout and electronic storage. Demonstrates correctly for removing stored data for the next user. Demonstrates correctly for removing stored data for the next user.					