



RISE-1205CXA-ACCY01
Accessory Kit

Part #	Description	Qty	
RISE-1205CXA-MAN01	Operators Manual for Riser Bond 1205CXA	1	
RISE-1205CXA-STRAP01	Instrument Shoulder Strap (attached) for 1205CXA	1	
GENE-12VDC-.75A	AC Adapter/Battery Charger 12VDC 750mA	1	
RISE-1205CXA-BAG01	Clip-On Accessory Bag/Pouch	1	
PAST-PE9741	Adapter, 75 ohm BNC(m)-F(f)	1	
RISE-WAVE-VIEW	WAVE-VIEW(Ver.2.06 Software for Windows (1 disk)		

RISE-1205CXA-ACCY01
 Accessory Kit

Part #	Description	Qty	
RISE-250-0025-02	Operators Manual for WAVE-VIEW Software	1	
RISE-220-0007-00	Coax VOP Ref Card (attached to instrument handle)	1	
GENE-F-CABLE-60	Type F(m) Push-On Cable, 60"	1	
GENE-DB9(M)-DB9(F)	DB9(m) to DB9(f) RS232 Cable, Straight Through	1	